

SkiGear Co.  
1661 Mesa Drive  
Las Vegas, Nevada  
123-555-5555

## EQUIPMENT INSPECTION

MACHINE	SERIAL NUMBER	INSPECTION GRADE
Injection Molder	SGMM-12345	FAIL

### INSPECTION SUMMARY

During the inspection of the injection molder, a notable issue came to light concerning one specific part of the machine. The nozzle was found to be clogged, leading to the production of defective parts. A thorough examination was conducted and discovered residual material obstructing the nozzle's proper function. Responding promptly, the nozzle was, effectively restoring its optimal performance. Consequently, the machine was able to resume production, producing high-quality parts once again. To prevent similar occurrences in the future, regular maintenance is strongly. Overall, the identification and swift resolution of the issue ensured uninterrupted production without any further delays or compromised output.

Injection Unit	Defective	X
Mold Clamping Unit	Good	✓
Hydraulic System	Good	✓
Temperature Control System	Good	✓
Ejector System	Good	✓
Lubrication System	Good	✓
Safety Devices	Good	✓
Control Software	Good	✓

Emily Johnson  
Inspected by

2022-03-01  
Date